

| ARMOR REPLACEMENT COILS | | | | |
|-------------------------|-------------|------------------------|---|---------------------|
| Adams part no. | Description | Current Armor part no. | Former Armor part numbers | K.M. White part no. |
| K1101 | 270VDC | 10470-01 | 0158 002, 140-6011-01, MC1000 | LA 201 |
| K1102 | 80VDC | 10471-01 | 0158 003, 140-6011-03, MC218 | CLN2 |
| K1103 | 270VDC | 10473-01 | 0158 005, 140-6006-05, AR 7240 | LA 124 |
| K1104 | 80VDC | 10477-01 | 0158 010, 140-6006-03, AR 324 | LA 462 |
| K1105 | 7VDC | 10478-01 | 0158 011, 140-6006-01, AR 14 | LA 411 |
| K1106 | 110VDC | 10501-01 | 0158 041, 140-6006-07, AR 683 | — |
| K1107 | 110VDC | 10476-01 | 0158 008, 140-6006-09, AR 2000 | LA 100 |
| K1108 | 240VDC | 10472-01 | 0158 004, 140-6011-02, MC2500 | LA 127 |
| K1110 | 270VDC | 10474-01 | 0158 006, 140-6006-04, AR 4840 | LA 226 |
| K1111 | 60VDC | 10475-01 | 0158 007, 140-6006-08, AR 450 | LA 219 |
| K2101 | 140VDC | 10480-01 | 0158 013, 140-6003-03 | LA 1331 |
| K2102 | 110VDC | 12076-01 | 0158 025, A28742P1, 0158 039, A41042P1, 0158 053, A47451P1, 139-003-01, 140-6003-01 | LA 1401 |
| K2103 | 55VDC | 10745-01, 12076-02 | 0158 026, A28742P2, A41042P2, 0158 054, A47451P2, 139-0003-02, 140-6003-02 | LA 1402 |
| K3101 | 55VDC | 12077-02 | 140-6021-02, 6021.02QC | |
| K3102 | 110VDC | 12077-01 | 140-6021-01, 6021.01QC | |



**10604-01
Coil
110VDC**



**13036-01
Coil
110VDC**



**10470-01
K1101**



**10474-01
K1110**



**10477-01
K1104**



**10473-01
K1103**



**10480-01
K2101**



**12076-02
K2103**



**10472-01
K1108**



**10476-01
K1107**



**10501-01
K1106**



**10471-01
K1102**



**12076-01
K2102**



**10475-01
K1111**



**10478-01
K1105**



**12077-02
K3101**

**12077-01
K3102**