



Westinghouse EC relays come with permanently installed coils. Coils cannot be replaced. Order complete replacement relays from table below.

TYPE EC RELAYS			
Adams part no.	Contact configuration	Coil voltage	Westinghouse part no.
W245G02	2M/0B	125.0VDC	324C981G20
W245G04	4M/0B	125.0VDC	324C981G40
W245G22	2M/2B	125.0VDC	324C981G22
W245G24	4M/2B	125.0VDC	324C981G42
W245G26	6M/2B	125.0VDC	324C981G62
W245G33	3M/3B	125.0VDC	324C981G33
W245G35	5M/3B	125.0VDC	324C981G53
W245G44	4M/4B	125.0VDC	324C981G44
W246G26	6M/2B	62.5VDC	324C981G62
W246G44	4M/4B	62.5VDC	324C981G44

See WVP2030 Value Pak below.



### EC RELAY REPAIR PARTS

**W225.** Movable contact bridge assembly. Replaces Westinghouse part no. K7310-G01.

**W226A.** Stationary contact, top make/bottom break; makes with W225. Replaces Westinghouse part no. 630B611-G01 (formerly K7307-G1).

**W226B.** Stationary contact, top break/bottom make; makes with W225. Replaces Westinghouse part no. 630B611-G02 (formerly K7307-G2).

**W228.** Fingerboard assembly with Bakelite base and leaf spring; receives W225 contact bridge assemblies. Replaces Westinghouse part no. K7305-G01.

### WVP2030 EC RELAY VALUE PAK REPAIR KIT

Here's an economical 100-piece assortment of the frequently-needed repair parts shown above. Put a Value Pak in every route truck, and save time and money on simple repairs. Components pictured are also sold separately above.



Adams part no.	Includes	Description	Quantity
WVP2030	W225	Contact bridge assembly	25
	W226A	Stationary contact, top make/bottom break	50
	W226B	Stationary contact, top break/bottom make	20
	W228	Fingerboard assembly	5