

# Value Paks for A6164BP Switches

Each of the Paks described below features 20-250 each of the movable contacts, stationary contacts and shunts you need most to repair Otis A6164BP switches.

Stock a Repair Pak for convenience.

**OVP2110 VALUE PAK**

Adams part no.	Otis part no.	Quantity
<b>O21C4</b>	150P4	250
<b>O21C5</b>	93D2	50

**MOVABLE CONTACT VALUE PAK**

Adams part no. OVP2110 Value Pak. Contains 250 movable contacts + 50 leaf springs.

*O21C4 movable contact, both sides shown*

*O21C5 leaf spring*

**STATIONARY CONTACTS VALUE PAK**

Adams part no. OVP2111 Value Pak. Contains 225 stationary contacts.

Adams part no.	Otis part no.	Quantity
<b>O21C2</b>	150P26	100
<b>O21C3</b>	150P27	100
<b>O21C1</b>	150P25	25

**OVP2111 VALUE PAK**

*O21C2*

*O21C3*

*O21C1*

**SHUNTS VALUE PAK**

Adams part no. OVP2112 Value Pak. Contains 160 shunts.

Adams part no.	Otis part no.	Length	Quantity
<b>O521A</b>	175J88	3 <sup>3</sup> / <sub>4</sub> "	20
<b>O521B</b>	175J89	4 <sup>3</sup> / <sub>4</sub> "	100
<b>O521C</b>	175J90	5 <sup>3</sup> / <sub>4</sub> "	20
<b>O521D</b>	175J122	7 <sup>5</sup> / <sub>8</sub> "	20

**OVP2112 VALUE PAK**

*O521D*

*O521B*

*O521C*

*O521A*