


REPAIR PAK FOR ADAMS O2200 SWITCHES



Best use: Keep one or more Repair Pak at every job site ...and eliminate trips back to the warehouse.

Adams part no. OK2220 Repair Pak.

Contains items (1) thru (16).

Photo key	Adams part no.	Otis part no.	Description	Quantity
1	O22A2	A245AE1	Armature	1
2	O22A3	384FS1	Brass guard	2
3	O22B1	306BR1	Movable contact base	1
4	O22BA1	6810A1	Auxiliary contact assembly	2
5	O22C1	153Z1	Movable copper contact	15
6	O22C3	150Y4, Y8	Movable copper contact with 3/8" dia. silver tip	6
7	O22C4	150C13	Stationary auxiliary contact	2
8	O22C5	150C14	Stationary auxiliary contact	2
9	O22D1	154AB1	Stationary carbon contact	15
10	O22D4	150W6	Stationary threaded contact with 3/8" dia. silver tip	6
11	O22H1	276H1	Arc barrier	2
12	O22H2	6534B1	Arc deflector	1
13	O22K1	179AK2	Carbon holder	1
14	O22K2	A336BR1	Carbon clamp	1
15	O546B	176KA13	Connector, 6 3/8"L	3
16	OVP2205*	—	Assorted hardware & springs*	1 pkg

*See below for description.


VALUE PAKS FOR ADAMS O2200 SWITCHES

Each of the Paks described below features 10-250 each of the contacts and hardware you need most to repair Otis 6754-series switches.



OVP2205 Hardware Pak. Incl. All parts listed to the right.

Adams part no.	Otis part no.	Description	Qty.
O21P2	99G1	Terminal stud, 1 3/8"L	20
O22P3	99G2	Terminal stud, 2"L	20
O22R1	141Y1	Rivet for O22S1, 1 1/8"L	10
O22S1	90TA3	Compression spring	50
O22S2	90VA16	Compression spring	20
O22T1	464BJ2	Fiber separator	50
O22W2	128H1	Washer	50
—	—	#8-32 nuts	100



Each Value Pak consists of 100 or 250 ea. of the following contacts:

Adams part no.	Otis part no.	Description
O22C1	153Z1	Movable copper, 2 3/4"L
O22D1	154AB1	Stationary carbon

OVP2201 Value Pak. 100 of each.

OVP2202 Value Pak. 250 of each.